


steering ball housing and the neck of the steering ball are in contact. In this case, IMMEDIATE ACTION must be taken to fit replacement ball joint assemblies as detailed in Bulletin Item No.30.



Item No.41. DELETION OF STEERING ROD COVER (PART NO.50570)
- ALL MODELS.

With the introduction of the adjustable type Steering Ball Joint (Part No.54012) from Engine No. EO/PB/10789, the fitting of the Steering Rod Covers (Part No.50570) will be discontinued.

Please refer to Spares Note 64 for Parts Change Information.