

angles to each other, as shown below.

Arrangements have been made for the modified brackets to be supplied from our Spares Dept.

